


USE & CARE GUIDE




In order to clean the vanity top, please only use a soft cotton cloth or soft sponge.



Never use acidic, alkali, or any products to clean the vanity top that state on their label that they are not suitable for use on Acrylic, ABS, Polystyrene or Plastic



In order to remove light marks or scratches, apply toothpaste to the area and scrub with a soft cloth or sponge.



It is advised to clean the surface of the vanity top regularly in order to remove any insoluble products. Warm soapy water should be used and afterwards the bath should be wiped. **Do not let cleaners soak in.**




It is advised to always run some cold water before turning on the hot tap, with hot water temperatures not exceeding 65 Celsius



If deep scratches or burns appear, please use sandpaper with at least 1500 grit. Dampen the sandpaper slightly with water and then proceed to rub the sandpaper in a circular motion around the affected area, ensuring that you rub slightly wider than the affected area.


Continue doing so until the scratch is no longer visible. In order to bring the affected area back to its shiny form, please use a soft cloth and a small amount of polish to buff the rubbed area. Continue doing so until the affected area is restored to its original shine.



The surface of the vanity top has good resistance properties to acids, but should not come into contact with alkalis or organic solvents, such as caustic soda, some multi-surface cleaners, bathroom cleaners, bleaches, harsh solvents, burning cigarettes, strong chemicals such as dry-cleaning fluids, paint strippers, acetone, citrus based chemicals, and nail/varnish remover.



Please read all instructions carefully before proceeding with installation.




Afin de nettoyer la dessus de vanité, veuillez utiliser un tissu en coton ou une.



Ne jamais utiliser de produits acides, alcalins ou autres substances qui ne sont pas compatibles avec de l'acrylique, ABS, polystyrène ou plastique.



Afin de nettoyer des traces ou rayures, appliquer du dentifrice sur la zone et nettoyer avec un tissu ou une éponge.



Il est conseillé de nettoyer la dessus de vanité régulièrement afin de se débarrasser des produits insolubles. Nettoyer la dessus de vanité avec de l'eau chaude et du savon puis sécher la dessus de vanité. **Ne pas laisser les produits ménagers sur la surface de la dessus de vanité**




Il est conseillé de faire couler un peu d'eau froide avant de faire couler de l'eau chaude, avec une température en dessous de 65 degrés celsius



Si des rayures plus profondes ou des marques de brulure apparaissent, utilisez du papier de verre 1500 grains minima. Humidifier le papier légèrement avec de l'eau puis frotter en rond autour de la zone endommagée, en frottant un peu plus large que la zone elle-même.

Continuer à frotter jusqu'à ce que la rayure ne soit plus visible. Afin de retrouver l'éclat original, utiliser un chiffon et un petit peu de vernis et appliquer sur la zone. Continuer jusqu'à ce que la zone retrouve sa brillance



La surface de la dessus de vanité résiste facilement aux produits acides, mais ne devrait pas être exposée aux produits alcalins, solvants bio, soude caustique, certains nettoyants multi-surface, certains produits d'entretien de salle de bain, javel, solvants agressifs, foyer de cigarette, liquide de nettoyage à sec, décapant à peinture, acétone, produit à base de citron, dissolvant.



Veillez lire les instructions avant installation